



COLOR CODE:

Airframe Service Bulletin Compliance Record		Pending
Aircraft:	Evektor SportStar Max	Recurring or Due
Serial No	2010-1306	Declined
Registr:	N24AV	Informational
Revised:	5-Jun-23	Not Applicable
		Complied with

Document	Date	Type	Subject	Applicable	Compliance	Date	By	Next Due
SportStar 001a	8-Apr-04	Mandatory	Elevator trim	if manual trim	n/a (electric trim)	20-Jul-15	LSRM 3550588	
SportStar 002a	3-Oct-05	Mandatory	radiator hose clnce	all SportStar	alt compl SI-EVSS-02	22-Dec-15	LSRM 3550588	
SportStar 003a	2-Dec-05	Mandatory	rescue sys	if rescue sys installed	n/a (no parachute)	20-Jul-15	LSRM 3550588	
SportStar 004a	3-Jan-06	Mandatory	canopy lock	wide locking canopy	n/a (composite)	20-Jul-15	LSRM 3550588	
SportStar 005a	14-Dec-06	Mandatory	bracket insp	all SportStar	c/w by inspection	21-Jul-15	LSRM 3550588	
SportStar 006a	11-Sep-08	Safety Alert	canopy bushes	composite canopy	n/a by mfg date	20-Jul-15	LSRM 3550588	
SportStar 006b	27-Dec-06	Informative	MTOW to 575 kg	if MTOW <575 kg	n/a, MTOW 600 kg	20-Jul-15	LSRM 3550588	
SportStar 007b	9-Sep-06	Information	Oil thermostat	all SportStar	n/a, already installed	20-Jul-15	LSRM 3550588	
SportStar 008b	16-Aug-07	Informative	Night VFR	all SportStar	n/a, night approv	20-Jul-15	LSRM 3550588	
SportStar 009b	1-Sep-08	Informative	nosewheel steering	optional	declined to modify	20-Jul-15	LSRM 3550588	
SportStar 010b	17-Feb-09	Informative	Matco parking brake	if std parking brake instal	n/a, already installed	20-Jul-15	LSRM 3550588	
SportStar 011a	9-Jun-09	Mandatory	3000 hr inspection	all SportStar	ck Hobbs, pending	20-Jul-15	LSRM 3550588	hobbs 3000
SportStar 011b	22-Jun-09	Informative	MTOW to 600 kg	if MTOW <600 kg	n/a, MTOW 600 kg	20-Jul-15	LSRM 3550588	
SportStar 012a	8-Aug-08	Mandatory	autopilot stops	if TruTrack autopilot	n/a, Dynon autopilot	20-Jul-15	LSRM 3550588	
SportStar 012b	8-Aug-08	Informative	Matco brakes	if std brakes installed	n/a, factory installed	20-Jul-15	LSRM 3550588	
SportStar 013b	12-Nov-09	Informative	Rudder pedal barrier	optional	n/a due ctr console	20-Jul-15	LSRM 3550588	
SportStar 014a	23-Jun-10	Mandatory	hose attachment	all acft mfg thru 6/2010	n/a per mfg date	20-Jul-15	LSRM 3550588	
SportStar 015a	23-Jun-10	Mandatory	lateral control jams	all SportStar w/ autopilot	n/a per mfg date	20-Jul-15	LSRM 3550588	
SportStar 017a	11-Jul-11	Safety Alert	rudder cable clamps	al SportStar	c/w by gluing stops	20-Jul-11	A&P 22633966	
SportStar 018a	30-Nov-11	Safety Related	crankshaft journal	n/a per Minnich LSRM	c/w per Max 002a	22-May-15	LSRM 3665330	
SportStar 019a	20-Jun-12	Safety Alert	fuel hose replacement	IAW Rotax ASB-912-061	n/a by pump p/n	27-Jun-15	LSRM 3550588	
SportStar 021a	16-Feb-13	Mandatory	loose fuel sel flanges	all SportStar	c/w per Max 004a	2-Jan-15	LSRM 3665330	
SportStar 022a	27-Jun-13	Safety Alert	canopy open in flight	metal frame canopy	n/a, composite	20-Jul-15	LSRM 3550588	
SportStar 023a	10-Jul-13	Safety Alert	canopy lock spring	metal frame canopy	n/a, composite	20-Jul-15	LSRM 3550588	
SportStar 024a	22-Jul-13	Service Bulletin	maint manual change	metal frame canopy	n/a, composite	20-Jul-15	LSRM 3550588	
SportStar 025a	5-Nov-14	Service Bulletin	fuel T and X fittings	all SportStar	c/w per Max 005a	2-Jan-15	LSRM 3665330	
SportStar 027a	10-Feb-13	Safety Alert	fuselage rivets	2006 and earlier	n/a, 2010 mfg	20-Jul-15	LSRM 3550588	
SportStar 028b	5-May-14	Notification Bul	demonstr x-wind	all SportStar	c/w per Max 006b	30-Jan-15	LSRM 3665330	
SportStar 029a	16-Jun-14	Safety Alert	canopy lock	composite canopy	c/w per Max 007a	30-Jan-15	LSRM 3665330	
SportStar 030a	16-Jun-14	Safety Alert	flap drive pins	all SportStar	c/w by inspection	5-Jun-23	LSRM 3550588	each cond insp
SportStar 031a	2-Mar-15	Safety Alert	change in CHT meas	n/a (old style heads)	c/w per Max 009a	22-May-15	LSRM 3665330	
SportStar 032a	18-May-15	Service Bulletin	clutch slipping	914 engine	n/a (912 engine)	12-Aug-15	LSRM 3550588	
SportStar 033a	23-Nov-15	Safety Alert	canopy latch	metal frame canopy	n/a, composite	28-Nov-15	LSRM 3550588	
SportStar 034a	26-Apr-16	Safety Alert	carb floats	per Rotax SB	n/a by carb s/n	3-Oct-16	LSRM 3550588	
SportStar 035a	31-Jan-18	Safety Related	Magnum 601	if rescue sys installed	n/a (no parachute)	14-Mar-18	LSRM 3550588	
SportStar 036b	30-Nov-17	Notification Bul	safety system	if safety sys installed	n/a (no parachute)	1-Jun-18	LSRM 3550588	
SportStar 037a	27-Nov-17	Service Bulletin	Nose gear torque arms	all Sportstar	deferred	1-Jun-18	LSRM 3550588	at disassembly
SportStar 040a	16-Jul-21	Service Bulletin	muffler tailpipe	Apr 18 - May 21 mufflers	n/a (Aug 2017)	14-Sep-21	LSRM 3550588	