



Engine Service Bulletin Compliance Record

Engine: Rotax 912ULS
Serial No 6776695
Registr: N24AV
Revised: 3-Oct-16

COLOR CODE:
Conditional
Recurring or Due
Optional & eligible
informational
Complied with
Not Applicable

<u>Document</u>	<u>Date</u>	<u>Type</u>	<u>Subject</u>	<u>Applicable</u>	<u>Compliance</u>	<u>Date</u>	<u>By</u>	<u>Next Due</u>
Rotax SB-912-033UL	1-Aug-02	Mandatory	gearbox inspection	yes, 100LL in use	Hobbs 588.1	3-Oct-16	Lockwood Svc	Hobbs 1188.1
Rotax SB-912-037UL	1-Oct-02	Optional	enhanced starter	yes	optional	22-May-15	A Minnich LSRM	
Rotax SB-912-040UL	2-Apr-15	Mandatory	new dip stick	n/a by s/n		27-May-16	HP Shuch LSRM	
Rotax SB-912-042UL R1	1-Apr-04	Mandatory	propeller backlash	if backlash occurs		22-May-15	A Minnich LSRM	on backlash
Rotax SB-912-043UL R1	28-Aug-06	Mandatory	coolant specification	yes, using Dexcool		22-Dec-15	HP Shuch LSRM	on coolant chg
Rotax ASB-912-051UL	1-Oct-06	Alert	magnetic plug	n/a by s/n		22-May-15	A Minnich LSRM	
Rotax SB-912-052UL	13-Jun-04	Optional	governors	n/a, no governor		22-May-15	A Minnich LSRM	
Rotax SB-912-057UL R1	24-May-16	Optional	TBO to 15 years	applies by s/n	maint manual update	13-Jun-16	HP Shuch LSRM	
Rotax SB-912-059UL	15-Nov-11	Mandatory	crankshaft journal	n/a by s/n		22-May-15	A Minnich LSRM	
Rotax ASB-912-060UL	26-Jan-12	Alert	oil pump bolt torque	n/a by s/n		22-May-15	A Minnich LSRM	
Rotax ASB-912-061UL R1	26-May-12	Alert	fuel pump hose	n/a by s/n		22-May-15	A Minnich LSRM	
Rotax SB-912-063UL R2	21-Aug-13	Recommen	fuel pump replacement	n/a by pump p/n		22-May-15	A Minnich LSRM	
Rotax SB-912-065UL R3	26-Mar-15	Mandatory	float buoyancy test	n/a by s/n		13-Jun-16	HP Shuch LSRM	
Rotax SB-912-066UL R1	23-Apr-15	Mandatory	CHT meas change	n/a by head p/n		22-May-15	A Minnich LSRM	
Rotax SB-912-067UL R1	26-Mar-15	Mandatory	exchange of floats	n/a by eng+carb s/n		22-May-15	A Minnich LSRM	
Rotax SB-912-068UL R1	23-Apr-15	Mandatory	engine type plate	n/a by head p/n		22-May-15	A Minnich LSRM	