

Prof.H. Paul Shuch  
Director of Maintenance  
AvSport of Lock Haven  
353 Proctor Street, Hangar One,  
Lock Haven PA17745  
USA

Our ref: 2010 1306\_N905SM\_firesleeve protection

Kunovice, 2016-01-06

**Subject: Letter of Authorization**

Aircraft: SportStar MAX, s/n 2010 1306, N905SM

Total flight time: 454 hours

We authorize Prof. H. Paul Shuch to install firesleeve (Aeroquip AE102-XX or equivalent) on fuel, oil and coolant hoses in above mentioned aircraft. The firesleeve should be located in places where the hoses could get to contact with high temperature of exhaust pipes, muffler or exhaust gases.

-The installation must be done by a qualified person with appropriate rating

-The installation must be recorded in Airplane Log Book

-The installation must be tested for non-interference with aircraft controls, components or function

-Weight and Balance data must be updated if weight difference is significant

Your faithfully

**EVEKTOR - AEROTECHNIK a.s.**

Okružní 234  
293 06 BRADLEC  
IČ: 255 60 280

-8-



Jiří Michalík  
Service manager  
Evektor-Aerotechnik a.s.  
686 04 Kunovice  
Czech Republic  
office: +420 572 537 316  
cell: +420 602 729 981  
e-mail: [jmichalik@evektor.cz](mailto:jmichalik@evektor.cz)