



Optional Equipment Service Bulletin Compliance Record

Aircraft: Evektor SportStar Max
Serial No 2010-1306
Registr: N24AV
Revised: 20-May-24

COLOR CODE:
Conditional
Recurring or Due
Optional & eligible
informational
Complied with
Not Applicable

<u>Document/Topic</u>	<u>Date</u>	<u>Mfgr</u>	<u>Equipment</u>	<u>Applicable</u>	<u>Compliance</u>	<u>Date</u>	<u>By</u>	<u>Next Due</u>
Servo SB	21-Jan-09	TruTrack	DSP C	all TruTrack servos	n/a; servo not Tru Track	29-Jun-15	LSRM 3550588	n/a
SB 0921 rev A	22-Jun-09	Garmin	SL30 nav/com	if mod AE not c/w	by insp - mod AE c/w	29-Jun-15	LSRM 3550588	n/a
SB 041212	12-Apr-12	Dynon	SkyView	firmware ver 3.3.0, 3.3.1	ver 16 installed	14-Feb-21	LSRM 3550588	n/a
TSB 102913	29-Oct-13	Dynon	SkyView	firmware ver 7.0.0	ver 16 installed	14-Feb-21	LSRM 3550588	n/a
TSB 030413 rev B	26-Mar-14	Dynon	SkyView	10" s/n<6000, 7" s/n<4000	n/a by MAC adr	14-Aug-15	LSRM 3550588	n/a
TSB 032714	26-Mar-14	Dynon	SkyView	if Garmin xponder	n/a; Dynon xponder	22-May-19	LSRM 3550588	n/a
TSB 032916	29-Mar-16	Dynon	SkyView	Software 14.0	n/a; ver 14.1 installed	14-Jun-16	LSRM 3550588	n/a
TSB SV-GPS-250	25-May-19	Dynon	SkyView	SV-GPS-250	n/a; SV-GPS-2020	7-Jun-19	LSRM 3550588	n/a
TSB 060619	3-Jun-19	Dynon	SkyView	SV-GPS-2020 firmware	2020 firmware installed	5-Mar-20	LSRM 3550588	n/a
TSB 080219	31-Aug-20	Dynon	SkyView	servo pulley SV42T	n/a; predates 12/13/11	5-Aug-19	LSRM 3550588	n/a
TSB 050620 rev E	2-Aug-19	Dynon	SkyView	Kavlico pressure sensors	n/a; Honeywell sensor	4-Jun-23	LSRM 3550588	n/a
TSB 030413 rev C	1-Mar-22	Dynon	SkyView	Circuit board repl	n/a by s/n or MAC adr	7-Jul-22	LSRM 3550588	n/a
TSB 050622	17-May-22	Dynon	SkyView	HDX displays	n/a; Skyview Classic	7-Jul-22	LSRM 3550588	n/a
TSB 104808-000	23-Oct-23	Dynon	Skyview	SV-AP panel	n/a by shipment date	3-Nov-23	LSRM 3550588	n/a