



Engine Service Bulletin Compliance Record

Engine: Rotax 912ULS
Serial No 5647224
Registr: N66AV
Revised: 15-Jun-15

COLOR CODE:

Future compliance
Recurring
Optional & eligible
informational

Complied with or n/a

<u>Document</u>	<u>Date</u>	<u>Type</u>	<u>Subject</u>	<u>Applicable</u>	<u>Compliance</u>	<u>Date</u>	<u>By</u>	<u>Next Due</u>
Rotax SB-912-029 R3	11-Jul-06	Mandatory	crankcase	n/a by s/n				
Rotax SB-912-030UL R1	1-Feb-04	Mandatory	Carb flange	n/a by s/n				
Rotax SB-912-033UL	1-Aug-02	Mandatory	gearbox inspection	applies; using 100LL	hobbs 1594.4	17-Jul-14	Lockwood	hobbs 2194.4
Rotax SB-912-036UL R1	1-Aug-02	Mandatory	venting of oil system	superseded by SB-912-040UL				
Rotax SB-912-037UL	14-Dec-09	Optional	electric starter	applicable by s/n	eligible, declined			
Rotax SB-912-040UL	1-Apr-03	Mandatory	new oil dipstick	applicable by s/n	verified by inspection	13-Apr-10	owner/oper	
Rotax SB-912-041UL R1	14-Dec-09	Optional	TBO to 1500 hour	already accompl. by s/n				
Rotax SB-912-043UL R1	28-Aug-06	Mandatory	coolant specification	applies to all 912	rad. cap replaced	unknown	Mid Island	
Rotax SB-912-048UL	23-Sep-05	Mandatory	pin in carburettor	n/a by s/n				
Rotax SB-912-051UL	30-Jan-08	Mandatory	magnetic plug	applies by s/n	hobbs 1740.7	14-Jun-15	Shuch/LSRM-A	hobbs 1790.7
Rotax SB-912-052UL R1	29-May-07	Optional	governors	n/a (no governor installed)				
Rotax SB-912-053UL	13-Apr-07	Mandatory	fuel pump	applies by s/n	hobbs 685.6	30-Jun-10	Nippenose	
Rotax SB-912-054UL	29-May-07	Mandatory	fuel line	n/a by s/n				
Rotax SB-912-055UL	31-Aug-07	Mandatory	fit of oil filter	n/a by s/n				
Rotax SB-912-056UL	09.01.2008	Mandatory	propeller gear box	applies by s/n	hobbs 391	13-May-08	Lockwood	
Rotax SB-912-057UL	14-Dec-09	Optional	TBO to 2000 hour	eligible by s/n	hobbs 650.4	13-Apr-10	Nippenose	
Rotax SB-912-058UL	15-Apr-11	Mandatory	washer replacement	n/a by s/n				
Rotax SB-912-059UL	15-Nov-11	Mandatory	crankshaft journal	n/a by s/n				
Rotax ASB-912-060UL	26-Jan-12	Mandatory	oil pump bolt torque	n/a by s/n				
Rotax ASB-912-061UL	26-May-12	Mandatory	fuel pump hose	n/a by s/n				
Rotax ASB-912-062UL R1	5-Mar-13	Mandatory	cylinder head leak	n/a by s/n				
Rotax ASB-912-063UL R1	24-Jun-13	Recommen	fuel pump replacement	applies by s/n	hobbs 1431.0	29-Jul-13	Shuch/LSRM-A	
Rotax SB-912-065UL R2	27-Feb-15	Mandatory	carb float buoyancy	n/a by s/n				
Rotax SB-912-066UL	8-Dec-14	Mandatory	CHT meas change	n/a; old style heads				
Rotax SB-912-067UL	27-Feb-15	Mandatory	exchange of floats	n/a by s/n				
Rotax SB-912-068UL	15-Apr-15	Mandatory	engine type plate	n/a; old style heads				
Rotax SI-912-018	23-Jan-07	svc instruc	purging lubrication sys	when sys opened	hobbs 1740.7	14-Jun-15	Shuch/LSRM-A	hobbs 1790.7
Rotax SI-912-021	9-Oct-09	svc instruc	carb inspection	every 200 hours	hobbs 1649.9	11-Sep-14	Shuch/LSRM-A	hobbs 1849.9