

Prof.H.Paul Shuch,Ph.D.  
AvSport of Lock Haven  
353 Proctor Street, Hangar1  
Lock Haven  
PA 17745  
USA

Our ref: 2006 0810\_N66AV\_Bulletin Sportstar-002a

Kunovice, 2012-11-16

**Subject: Letter of Authorization**

Aircraft: SportStar s/n 2006 0810, N66AV

Based on Optional Service Instruction Av Sport SI-EVSS-02 issued by H.Paul Shuch,Ph.D. Director of Maintenance, AvSport of Lock Haven, LSRM-A,3550588, dated 12 November 2012 we authorize this alternate method of compliance with Evektor Mandatory Service Bulletin Sportstar-002a in above mentioned aircraft. This method is based on installation of fire sleeve over the left rubber radiator hose protecting the hose from damage caused by the exhaust pipe proximity.

- The installation must be done by a qualified person with appropriate rating
- The installation must be recorded in Airplane Log Book
- Weight and Balance data must be updated if weight difference is significant

Your faithfully

**EVEKTOR - AEROTECHNIK a.s.**  
**AVIATION SERVICE**  
Letecká 1384  
**CZ-686 04 KUNOVICE**



Jiří Michalík  
Service manager  
Evektor-Aerotechnik a.s.  
686 04 Kunovice  
Czech Republic  
office: +420 572 537 316  
cell: +420 602 729 981  
e-mail: [jmichalik@evektor.cz](mailto:jmichalik@evektor.cz)