

Letter of Authorization

Aircraft: Evektor Sportstar Plus, Sportstar SL, Sportstar MAX.

We authorize relocation of the oil pressure sensor to the firewall according to

AvSport SI-EVSS-01 "EVEKTOR SPORTSTAR MODIFICATION –RELOCATION OF OIL PRESSURE SENSOR TO FIREWALL" optional service instruction issued by H.Paul

Shuch, Ph.D. Director of Maintenance, AvSport of Lock Haven on September 13, 2012

Purpose: To increase oil pressure sensor durability.

The work must be carried out by any qualified Light Sport Repairman or A&P-AI

and it must to comply with ASTM Standard - F2245-04 Specification for Design and Performance of a Light Sport Airplanes.

Your faithfully

EVEKTOR - AEROTECHNIK a.s.
Kunovice, Letecká čp. 1384,
PSČ 686 04
IČO: 25 58 02 80
-2-


Jiri Michalik
Service Manager