

Airframe Service Bulletin Compliance Record

Aircraft: Bristell NG5 SLSA TDO

 Serial No
 093/2014

 Registr:
 N593BL

 Revised:
 6-May-23

<u>Document</u>

SA-5-0001-2017 SA-5-0005-2020

SA-0001-2020R1 SA-0002-2021

<u>Date</u>	<u>Type</u>
5-Oct-17	safety alert
11-May-20	safety alert
4-Sep-20	safety alert
11-Nov-21	safety alert

<u>Subject</u>		
elevator control stuck		
Kavlico sensors		
simplify wt/bal calc		
seat attachment		

Applicable		
	n/a: Rotax 912ULS	
	applies: has 2 Kavlicos	
	applies: all NG-5 variants	
	all UL and LSA models	

COLOR CODE:

Pending
Recurring or Due
Declined
Informational
Not Applicable
Complied with

Compliance	<u>Date</u>	<u>By</u>	Next Due
	20-Mar-21	LSRM 3550588	
inspected: no leaks	6-May-23	LSRM 3550588	next inspection
revised all wt/bal docs	20-Mar-21	LSRM 3550588	
install new LH brackets	12-Mar-23	LSRM 3550588	