



Airframe Service Bulletin Compliance Record

Aircraft: Evektor SportStar Max
Serial No 2006-0810
Registr: N66AV
Revised: 23-Oct-13

COLOR CODE:

Pending

Recurring or Due

Declined

Informational

Not Applicable

Complied with

<u>Document</u>	<u>Date</u>	<u>Type</u>	<u>Subject</u>	<u>Applicable</u>	<u>Compliance</u>	<u>Date</u>	<u>By</u>	<u>Next Due</u>
SportStar 001a	8-Apr-04	Mandatory	Elevator trim	n/a (electric trim)				
SportStar 002a	3-Oct-05	Mandatory	radiator hose clnce	recurrent @ oil filter repl	alternate per LoA	12-Nov-12	Shuch/LSRM-A	
SportStar 003a	2-Dec-05	Mandatory	rescue sys	n/a (not installed)				
SportStar 004a	3-Jan-06	Mandatory	canopy lock	previously performed	verified by inspection	31-Mar-10	owner/oper	
SportStar 005a	14-Dec-06	Mandatory	bracket insp	all SportStar	tach 387.5	2-Jul-08	Mid Island	
SportStar 006a	11-Sep-08	Mandatory	canopy bushes	n/a (SportStar SL only)				
SportStar 006b	27-Dec-06	Informative	MTOW to 575 kg	n/a (already at 575)				
SportStar 007b	9-Sep-06	Information	Oil thermostat	previously performed	verified by inspection	8-Sep-10	owner/oper	
SportStar 008b	16-Aug-07	Informative	Night VFR	optional, eligible by s/n	hobbs 634.9	31-Mar-10	owner/oper	
SportStar 009b	1-Sep-08	Informative	nosewheel steering	optional	not performed			
SportStar 010b	17-Feb-09	Informative	Matco parking brake	optional	n/a (no parking brake)			
SportStar 011a	9-Jun-09	Mandatory	3000 hr inspection	all sportStar	pending			hobbs 3000
SportStar 011b	22-Jun-09	Informative	MTOW to 600 kg	optional	hobbs 914.3	5/5/2011	Shuch/LSRM-A	
SportStar 012a	8-Aug-08	Mandatory	autopilot stops	n/a (no autopilot installed)				
SportStar 012b	8-Aug-08	Informative	Matco brakes	n/a (Grove brakes)				
SportStar 013b	12-Nov-09	Informative	Rudder pedal barrier	optional	kit acquired, pending			
SportStar 014a	23-Jun-10	Mandatory	hose attachment	all SportStar to Jun 2010	hobbs 933.5	5/5/2011	Shuch/LSRM-A	
SportStar 015a	23-Jun-10	Mandatory	lateral control jams	n/a (no autopilot installed)				
SportStar 017a	11-Jul-11	Mandatory	rudder cable clamps	all SportStar	hobbs 959.6	7/20/2011	Shuch/LSRM-A	
SportStar 018a	30-Nov-11	Mandatory	crankshaft journal	n/a (original crankshaft)				
SportStar 019a	20-Jun-12	Mandatory	fuel hose replacement	n/a (different fuel pump)				
SportStar 021a	16-Feb-13	Mandatory	loose fuel sel flanges	applies	pending next insp			
SportStar 022a	27-Jun-13	Mandatory	flight manual change	applies	c/w by adding pages	10/23/2013	Shuch/LSRM-A	
SportStar 023a	10-Jul-13	Mandatory	canopy lock spring	applies	c/w by inspection	10/23/2013	Shuch/LSRM-A	
SportStar 024a	22-Jul-13	Mandatory	maint manual change	applies	c/w by adding pages	10/23/2013	Shuch/LSRM-A	