



Prof. H. Paul Shuch
Director of Maintenance
AvSport of Lock Haven
353 Proctor Street, Hangar One,
Lock Haven PA17745
USA

Our ref. 2010 1306_N24AV_Multi-Function Display

Kunovice, 2020-03-10

Subject: Letter of Authorization

Aircraft: SportStar MAX sn/ 2010 1306, N24AV
Total flight time: 1060 hours

We authorize Prof. H. Paul Shuch, 3550588 LSRM-A, or any other aviation maintenance technician with similar appropriate ratings, to perform the following avionics modification on the above mentioned aircraft:

Remove from instrument panel existing Multi-Function Display, Dynon SkyView SV-D700
Install in instrument panel replacement Multi-Function Display, Dynon SkyView SV-D1000

under the conditions as follows:

- The installation(s) must comply with ASTM Standard-F2245-04, Specification for Design and Performance of a Light Sport Aircraft
- The installation(s) to be done in accordance Dynon Avionics SkyView Installation Guide, Document 101320-031, Revision AF, for use with software version v15-4, November 2019
- The installation(s) must be tested for non-interference with aircraft controls, components, or function
- The alteration must be recorded in the Airplane Log Book
- Weight and Balance data must be updated if weight difference is significant

Yours faithfully

Dusan Zeman
After-Sales Support
Evektor-Aerotechnik a.s.
686 04 Kunovice
Czech Republic
office: +420 572 537 524
email: dzeman@evektor.cz

EVEKTOR - AEROTECHNIK a.s.
Okružní 234
293 06 BRADLEC
IČ: 255 60 280 -8-