

Prof.H.Paul Shuch 353 Proctor Street, Hangar 1 Piper Memorial Airport Lock Haven PA17745 USA

Our ref: 20060810_N66AV_Battery

Subject: MANUFACTURER'S AUTHORIZATION OF LSA ALTERATION

Evektor-Aerotechnik a.s., the manufacturer of SportStar Light Sport Aircraft, following the requirement §91.327 of the Sport Pilot Rule, does agree with the following alterations of the SportStar airplane, S/N 2006 0810, N66AV, 1344 hours total flight time:

- Replacement of the original Evektor UB12180 battery by Odyssey PC-680 battery, under the conditions as follows:
 - The installation(s) must be done by a qualified person with appropriate rating
 - The installation shall be done in accordance with instructions provided by the airplane manufacturer
 - The installation(s) to be also done in accordance with the installation manuals supplied with the instruments/equipment
 - The installation(s) must be checked / tested for proper and non-collision function by a qualified person with appropriate rating
 - The installation(s) must be recorded in the Airplane Log Book

- Weight and Balance data must be updated if applicable

Kunovice, 12 March 2013

EVEKTOR - AEROTECHNIK a.s. AVIATION SERVICE Letecká 1384 CZ-686 04 KUNOVICE Jiři Michalik

Service Manager

Evektor-Aerotechnik a.s.

686 04 Kunovice

Czech Republic

office: +420 572 537 316 cell: +420 602 726 362

e-mail: jmichalik@evektor.cz